

LOTTA CRABTREE HOUSE

Condition: fair altered original site

This building shows little of its original character.

Presently the walls are covered with asbestos shingles.

A modern porch has been built across the front ~~which~~ affording entrance to the several apartments it has been divided into.

It is two-storied with a gable roof and there is a shed roofed addition at the rear.